

To,

**THE DIRECTOR OF BOILERS, WEST BENGAL**

New Secretariat Building (8th floor)  
1, K.S. Roy Road, KOLKATA - 700001

Sir,

Name of the Owner: 7 MILLION

Locality: 1/1 Kalitala lane , P.O : Baidyabati, Hooghly, Pin : 712222

Boiler Maker's No: PTPL-08/205, Boiler Type: **Package**, Date of Inspection: **12-12-2019**

**Sub:- Dry and Through inspection of boiler.**

Reference to above and my subsequent visit to above premises this is to report that the above mentioned boiler was inspected thoroughly in dry condition and found as follows:-

- i) The Boiler was laid on it's foundation.
- ii) General condition of the boiler pressure parts were found to be in order and in dent free condition.
- iii) Leading dimensions of boiler pressure parts and the Facsimile on boiler were checked with approved pressure parts drawings and form-II respectively and found to be in order.
- iv) No steam or feed water pipe was connected with the boiler..
- v) All mountings & fittings of the boiler supported by IBR test certificates were inspected and found to be in order.

In view of the above owners may now be advised to get the approval of Steam and feed water piping drawings and procure the materials for erection of the same as per IBR.

Provisional Order for steaming is kept withheld pending the followings-

- i. Approval of Steam and feed water piping drawings.
- ii. Fabrication of boiler proper and steam and feed water line in approved manner.
- iii. Satisfactory hydraulic test of the boiler alongwith the steam and feed water pipe lines.
- iv. Approval of form-III A of pipe lines.

Your's faithfully

Sri Subhashis Das, Assistant Director of Boilers, W.B.

**No. WB/R/2019/1546.date 13-12-2019**

Copy forwarded for information and necessary action to:-

- i) **7 MILLION**, 1/1 Kalitala lane , P.O. : Baidyabati, Hooghly, PIN : 712222
- ii) Sri Subhashis Das, Assistant Director of Boilers, W.B.

Joint Director of Boilers, W.B.