

To,

THE DIRECTOR OF BOILERS, WEST BENGAL

New Secretariat Building (8th floor)
1, K.S. Roy Road, KOLKATA - 700001

Sir,

Name of the Owner: 7 MILLION

Locality: 1/1 Kalitala lane , P.O : Baidyabati, Hooghly, Pin : 712222

Boiler Maker's No: PTPL-08/205, Boiler Type: **Package**, Date of Inspection: **24-12-2019**

Sub: Fit Up Inspection of pipe line

ref: 1) owners letter no-nil dt 23.12.19

2) office report no- WB/R/2019/1558 dt 16.12.19

3) erectors approval no- WB/REPAIR-FINAL/2019/239 dt 7.12.19

4)approved drg: MEC/7M/SP/B01/19 (R-0) & MEC/7M/FP/B02/19

5) lab test report no- Lab/test/409/a/173 dt 20.12.19

With reference to above, this is to report that the

1. balacne flange material were inspected along with IBR TC as per attached annexure and found to be in order .

2) flange joint of steam and feed pipe lines were inspected in tack fit up condition as per approved drawing and found to be in order.

In view of the above, owners may now be advised to complete the welding and offer the boiler for hydraulic test.

Your's faithfully

Sri Subhashis Das, Assistant Director of Boilers, W.B.

No. WB/R/2019/1628.date 25-12-2019

Copy forwarded for information and necessary action to:-

i) **7 MILLION**, 1/1 Kalitala lane , P.O. : Baidyabati, Hooghly, PIN : 712222

ii) Sri Subhashis Das, Assistant Director of Boilers, W.B.

Joint Director of Boilers, W.B.