

To,

THE DIRECTOR OF BOILERS, WEST BENGAL
New Secretariat Building (8th floor)
1, K.S. Roy Road, KOLKATA - 700001

Sir,

Name of the Owner: 7 MILLION

Locality: 1/1 Kalitala lane , P.O : Baidyabati, Hooghly, Pin : 712222

Boiler Registration No: WBL13297, Boiler Type: **Package**, Date of Inspection: **16-08-2021**

Sub: Steam Test

Ref: i) Owners Letter No. nil dt 09.08.2021

Reference above and my subsequent visit to above premises this is to report that the steam test of the boiler of working pressure 10.54 (Kg/cm²) was performed and found as follows;

Safety Vv Details	Pop up Pr	Reset Pr.	Blow down
Double post	(Kg/cm ²)	(Kg/cm ²)	(%)
Front :Seat dia 25.mm	10.4	10	3.84%
Rear : Seat dia 25.mm	10.54	10.2	3.22%

During the test, mountings & fittings were performed satisfactorily and no pressure accumulation was observed and found to be in order.

Yours faithfully,

Deputy Director of Boilers, W.B.

No. WB/R/2021/0945.date 17-08-2021

Copy forwarded for information and necessary action to:-

i) **7 MILLION**, 1/1 Kalitala lane , P.O. : Baidyabati, Hooghly, PIN : 712222

ii) Sri Rajkumar Paul, Deputy Director of Boilers, W.B.

Joint Director of Boilers, W.B.