

To,

THE DIRECTOR OF BOILERS, WEST BENGAL

New Secretariat Building (8th floor)
1, K.S. Roy Road, KOLKATA - 700001

Sir,

Name of the Owner: 7 MILLION

Locality: 1/1 Kalitala lane , P.O : Baidyabati, Hooghly, Pin : 712222

Boiler Registration No: WBL13297, Boiler Type: **Package**, Date of Inspection: **30-04-2021**

Sub: Steam Test of boiler

Ref: i) Owners Letter No.nil dt 27.04.21

Reference above and my subsequent visit to above premises this is to report that the steam test of the boiler of working pressure 10.54 Kg/cm² was found satisfactory..

The results of steam test were as follows:

Safety Vv Details	Pop up Pr	Reset Pr.	Blow down
25.4 mm dia. double post	(Kg/cm ²)	(Kg/cm ²)	(%)
Front	10	9.2	8
Rear	10.54	9.8	7

All mountings & fittings were performed satisfactorily during the steam test, and no pressure accumulation was observed.

Yours faithfully,

Deputy Director of Boilers, W.B.

No. WB/R/2021/0563.date 03-05-2021

Copy forwarded for information and necessary action to:-

i) **7 MILLION**, 1/1 Kalitala lane , P.O. : Baidyabati, Hooghly, PIN : 712222

ii) Sri Rajkumar Paul, Deputy Director of Boilers, W.B.

Joint Director of Boilers, W.B.